


# Foreword

- Bolt, nut tightening portion

Bolt	  BS-04481	  BS-04483
Nut	  BS-04482	

## B: CAUTION

Since there is a possibility that the required strength will not be obtained, an inverter welder must be used for spot-welding at locations where high-strength steel is used.