
B: INSTALLATION

Overall view



- 20 mm (0.79 in)
- (1) 1 point (service) 8 points

(2)

- (3) 3 points
- (4) 1 point

- 2 points
- 2 points (service)


Note: Apply a panel bonding adhesive to part "a".

[e] Spot welding conditions

Compression: 3.5 kN, Current: 7.5 kA, Welding time: 16 cyc

Panel Replacement

• Views 1




- (A) 70 mm (2.76 in)
- (1) 2 points (service)
- (3) 3 points (service)
- (4) 1 point

(2) 7 points

Panel Replacement

• Views 2



(1)	points

(4)

1 point (service) (7)

1 point (service · matching) (2)


7 points (5)

3 points (8)

(3) 1 point (6) 2 points

[c] Spot welding conditions Compression: 3.0 kN, Current: 6.5 kA, Welding time: 25 cyc Compression: 3.5 kN, Current: 7.5 kA, Welding time: 16 cyc [e] Spot welding conditions

Panel Replacement



(1) 1 point (2) 2 points (3) 1 point (service · matching)